



POLICE DEPARTMENT

9/15/2010

INSTRUMENT REPAIR WORK SHEET

DATE SENT TO CMI FOR REPAIR:

INSTRUMENT# 68-010779

DESCRIPTION OF PROBLEM:

Maintenance was performed on optical Bench

Sol'n Cal Failed - Slope & DA
all other readings OK

See documents attached

Thank you

Obtained by Perlmutter & McQuinn, P.C. in Law Offices of Adam D. Perlmutter, P.C. v. NYPD, et al., Case No. 100220/2012 (N.Y. City S. Ct.). WWW.LEWYORKLEGALDEFENSE.COM - (212) 679-1990